


Parametrix, Inc. Midway Cap/555-1550-039(04) 3/00 (K)



**Figure 5-1.**  
**Post-Remedial Conditions**  
**(1998-1999), Hydrogeologic**  
**Section H-H', with Chloride**  
**Concentrations and**  
**Gas Probe Static-Pressure**  
**Measurements**  
**Midway Landfill**  
**Kent, Washington**




Figure 5-2.  
**Line of Geologic  
 Section Map  
 Midway Landfill  
 Kent, Washington**

Base Map Source: AGI (1990)





Figure 5-3.  
**Well Locations for Groundwater  
 Chemistry Monitoring  
 Midway Landfill  
 Kent, Washington**


- MW-16** ▲ Upper Gravel Aquifer Monitoring Well Number and Approximate Location
- MW-17B** ○ Sand Aquifer Monitoring Well Number and Approximate Location
- MW-14B** ● Southern Gravel Aquifer Monitoring Well Number and Approximate Location



Base Map Source: Supplemental Hydrogeologic and Hydrochemical Investigation, AGI, 1990

SCALE IN FEET






—x— Fenced Area Boundary

— Fluid Level Contour. Interval equals 10 feet. Contour placement is approximate.


- 40D 275.8 Well number and approximate location, showing leachate or groundwater elevation. Fluid elevations measured November 1998.
- 48S COND Condensate is present in well. Data point not used for potentiometric surface calculations.
- 54D DRY Well is dry. Data point not used for potentiometric surface calculations.

Approximate Area Where Potentiometric Surface is Below Refuse Based on Intersection of November 1998 Potentiometric Surface with Base of Refuse

Figure 5-4.  
**Shallow Groundwater/  
 Saturated Refuse Potentiometric  
 Surface Map - November 1998  
 Midway Landfill  
 Kent, Washington**



Parametrix, Inc. Midway Cap/555-1550-039(04) 3/00 (K)



- |            |  |
|------------|--|
| <b>NM</b>  | Chloride concentration not measured because well not part of the compliance monitoring network or insufficient water in well for sample collection |
| <b>ND</b>  | No data, measurement not collected   |
| <b>Dry</b> | No fluid detected  |
|            | Approximate UGA potentiometric surface, queried where inferred   |
|            | Approximate SA potentiometric surface, queried where inferred  |
|            | Approximate SGA potentiometric surface, queried where inferred   |






Figure 5-5.  
Pre-Remedial Conditions (1987), Hydrogeologic Section H-H', with Chloride Concentrations Midway Landfill Kent, Washington








Figure 5-8.  
**Generalized Southern Gravel Aquifer  
 Potentiometric Surface Map—  
 November 1998  
 Midway Landfill  
 Kent, Washington**

- MW-14B** ● Southern Gravel Aquifer Monitoring Well Number and Approximate Location
- 150— Approximate Potentiometric Surface Contour (in feet)
- (161.33) Measured Groundwater Elevation in Feet (November 9, 1998)
- ← General Direction of Groundwater Flow
- NM Water Level Not Measured
- (<188.7) Well was Dry, Elevation is Elevation of Bottom of Well
- \* Groundwater Level in These Wells Calculated Using Air Pressure Measurements at the Wellheads





**Landfill Gas System Gas Contours**  
*PRESSURE GRADIENTS 1QT, 1997*



SCALE 1:1000

The heavy contour line depicts the lateral extent of the vacuum in the Upper Gravel Aquifer beneath the landfill, which results from operation of the gas extraction system.



- Wells Presently Being Used for Human Drinking Supplies
- Wells Not Currently in Use for Human Drinking Supplies

Figure 6-1.  
**Private and Public Wells  
 Within One Mile of the  
 Midway Landfill**